

ISCO MODEL Signature SOFTWARE HISTORY

REVISION 1.31.036

Part # 60-4302-071

Software Release Date: 08/07/2018

Corrections:

- 1- Fixed an issue where Non-English languages were missing from version 1.30.
- 2- *10491/10161* Fixed an issue where the 306 sampler interface settings would not show up in the Program report.
- 3- *10366* Fixed an issue where the Signature would lock up after the first data push when configured for only Modbus input.
- 4- Updated boot code to support replacement flash memory chip

Enhancements:

- 1- Added support for LTE Modems.
- 2- *10213* Added support for maximum head settings for flow rate.
- 3- *10876* Added additional parameter adjustment for Laser Flow sensor - Stop Bin used to limit velocity sensing in certain difficult applications.
- 4- *10877* Added additional parameter adjustment for Laser Flow sensor - Minimum Doppler Power selection for use in certain difficult applications.