

## **ISCO MODEL DuraTracker SOFTWARE HISTORY**

**REVISION 1.01.002**

**Part# 60-4802-076**

**Software Release Date: 05/16/2023**

Corrections:

- 1- Force Battery Banks in Parallel when Non Ex-LaserFlow sensor is detected.
- 2- Improve Modem handling to allow for modems with inactive SIM cards to not impact battery life
- 3- Data Push Memory Management Error
- 4- Cycle TIENet power if LaserFlow sensor is reporting ultrasonic communication errors

Enhancements: Support for (TC1/TC4) WWG modems