

## **ISCO MODEL 6712 SOFTWARE UPDATES**

**REVISION 3.08.001**

**Software Release Date: 9/14/2022**

**Part# 60-9003-591**

**Corrections:** Fixed a shortcoming with the temperature code in 3.07. We had modified the Temperature to target a value that was 0.3°C below the configured temperature but it was bottoming out at 1°C. This fix allows it to hit a threshold that is below 1°C and hit a value that is 0.3°C below that configured value.

**Enhancements:** None