

## **ISCO MODEL 350 SOFTWARE HISTORY**

**REVISION 1.14.7**

**Part# 60-4302-072**

**Software Release Date: 02/19/2020**

Corrections:

- 1- Fixed issue that could result in 350 going off-line and requiring a power cycle to restore normal operation
- 2- Fixed issue that would hang the sensor up if a Diagnostic was run in open air.

Enhancements: None