

ISCO MODEL Signature SOFTWARE HISTORY

REVISION 1.36.001

Part # 60-4302-071

Software Release Date: 10/15/2021

Corrections:

- 1- (*IFLOW-592, IFLOW-337*) Fix issue relating to the ability for changing carrier settings with the LE910 TC4NAG Modem.
- 2- Prevents a 360EX with a 350EX from both firing at the same time and exceeding the limits of the EX barrier
- 3- Modem updates for to handle initial registration checks of HE910 reporting 0,0 before moving to the "default" value.

Enhancement: (*IFLOW-678*) All 3G - LTE modems outside of ELS31_V now configured for data centric per AT&T request.